


Non-Contact Infrared Thermometer

This infrared thermometer allows for non-contact temperature measurement. It features adjustable high and low temperature limits for alarms and a digital display for clear readings.



ADDITIONAL IMAGES

Eight functions

1. Emissivity Adjustable
2. Laser Positioning
3. Backlit display
4. Low Battery Prompt
5. High and Low Temperature Alarm
6. Unit Conversion
7. Automatic Shut-Down
8. Numeric Lock

PEAKMETER®

Product Overview

Professional Non-Contact Temperature Measurement

This non-contact infrared thermometer is designed for precise, safe temperature monitoring across a wide range of industrial and commercial applications. Featuring a 12:1 distance-to-spot ratio, it allows for accurate readings from a safe distance. The device is equipped with advanced functionality including adjustable emissivity, high/low temperature alarms, and a backlit digital display for clear visibility in various lighting conditions.

Measurement Performance

Temperature Range

-30 °C Min Temperature	380 °C Max Temperature
----------------------------------	----------------------------------

Distance-to-Spot Ratio	12:1
-------------------------------	------

Features & Functionality

Core Features

- Adjustable emissivity
- Laser positioning
- Backlit display
- Low battery prompt
- High and low temperature alarm
- Unit conversion (°C/°F)
- Automatic shut-down
- Numeric lock

Alarm Capabilities

Feature	Capability
Alarm Thresholds	Freely set upper and lower limits
Alert Trigger	Visual alarm when temperature exceeds or falls below set value