

Mercedes Benz Service Interval Reset Tool

This tool is designed for resetting service intervals on Mercedes Benz vehicles with a 38-pin connector, excluding ML class models. It allows users to reset the service indicator and clear airbag fault codes.



Product Overview

Professional Service Reset Solution

This diagnostic tool is engineered to streamline maintenance procedures for vehicles equipped with a 38-pin diagnostic connector. It provides a straightforward solution for resetting service indicators following routine maintenance, ensuring accurate vehicle tracking. Additionally, the device offers functionality to clear non-permanent airbag fault codes, helping technicians manage dashboard warnings efficiently.

Technical Specifications

Connector Interface	38-pin diagnostic connector
Compatibility Notes	Compatible with most models using 38-pin interface; excludes ML class
Key Functions	Service Interval Reset, Airbag Fault Clearing

Operational Guide

Operation Procedure

- Turn vehicle ignition on
- Connect tool to the 38-pin diagnostic port
- Wait for initialization (LED will turn red)
- Press the button for the desired operation
- Observe successful operation indicator (green light)